

Summary of CIAC Vehicles Repaint and Bodyworks

Vehicle	Job Description (Labor and Materials)
Toyota Hilux SHK 366	Body Painting <ul style="list-style-type: none"> - Bumper - Whole Bed - Roof
Toyota Hilux SHK 365	Body Painting <ul style="list-style-type: none"> - Bumper - 2 Door –RR - Quarter Panel - Roof - Whole Bed
Toyota Hilux SHK 363	Body Painting <ul style="list-style-type: none"> - 2 Bumper - 4 Door –LH and RH - Quarter Panel
Toyota Innova SKX 476	Body Painting <ul style="list-style-type: none"> - Front and Rear Bumper - LH Door Front and Rear - Quarter Panel - LH Fender
Toyota Hilux SHH 369	Body Painting <ul style="list-style-type: none"> - Front Bumper - Hood - Front Door - Whole Bed - Roof
Toyota Innova SHK 359	Replace/Install <ul style="list-style-type: none"> - Rubber Windshield External Detailing
Toyota Hilux SGR 832	Body Works and Paint Repair and Repaint all damage
Toyota Innova SGR 824	Body Painting <ul style="list-style-type: none"> - 2 Sides (LH and RH) - Front Bumper
Toyota Innova SHK 362	Bodyworks and Painting <ul style="list-style-type: none"> - Quarter Panel - 2 Bumpers - 2 Doors (LH) Bodyworks <ul style="list-style-type: none"> - RR LH Door
Toyota Innova SHK 364	External Detailing
Toyota Innova SGR 827/ABE 1144	Body Painting <ul style="list-style-type: none"> - RR Bumper

Vehicle	Job Description (Labor and Materials)
	<ul style="list-style-type: none"> - Front Bumper - LH Side - RH Side
Toyota Hilux SHK 367	Bodyworks (Tinsmith) <ul style="list-style-type: none"> - Roof - Quarter Panel Body Painting <ul style="list-style-type: none"> - Bumper - 2 Door –RR - Quarter Panel - Roof Whole Bed
Toyota Innova SGR 829	Bodyworks and Paint Repair and Repaint all damage External Detailing
Toyota Hilux CAJ 4377	Bodyworks and Paint Repair and Repaint all damage External Detailing
Nissan Navara CAI 5167	External Detailing