





NOTE:

- 1. DISTANCE OF SIGNS TO TAXIWAY 21M FROM TAXIWAY EDGE MARKINGS.
- 2. DISTANCE OF SIGNS TO RUNWAY 15M FROM RUNWAY EDGE MARKINGS.

- IF THIS DRAWING HAS BEEN RECEIVED ELECTRONICALLY, IT IS THE RECIPIENTS RESPONSIBILITY TO PRINT THE DOCUMENT TO THE CORRECT SCALE.
 THIS DRAWING SHOULD BE READ IN CONJUNCTION WITH OTHER RELEVANT DRAWINGS AND SPECIFICATIONS.
 ALL DIMENSION IN METER UNLESS OTHERWISE SHOWN.

CONSULTANTS:	DRAWN BY:	C.M.L.	SUBMITTED BY:
Urban Integrated Consultants, Inc. UICI Corporate Bldg., 8 Lands Street, VASRA, Diliman, Quezon City, 1128	CHECKED BY:	J.Q.G.	EFREN L. DAVID
	DWGS. CHK. BY:	A.T.C.	PRESIDENT - UICI

CLARK				
CLARK INTERNATIONAL AIRPORT				
CORPORATION				

COMMENDING APPROVAL:	APPROVED BY:	PROJECT TITLE :	PROJECT TITLE :	DRAWING STATUS:	FINAL	5
		CONSTRUCTION OF THE HORIZONTAL INFRASTRUCTURE PROJECT OF THE CLARK INTERNATIONAL AIRPORT NEW TERMINAL BUILDING PROJECT (FORMERLY CLARK AIRPORT LOW COST TERMINAL)		REVISION ⚠:	JULY 16, 2018	
JAIME ALBERTO C. MELO	ALEXANDER S. CAUGUIRAN			REVISION 📤 :	JULY 17, 2018	
VICE PRESIDENT RPORT OPERATION MANAGEMENT GROUP	PRESIDENT / CHIEF EXECUTIVE OFFICER	SHEET CONTENTS:	TAXIWAY GUIDANCE SIGNS LAYOUT			

